

Contact: Eric Mayne

### **Statement: Fuel-Pump Relay**

February 27, 2015, Auburn Hills, Mich. - FCA US LLC is voluntarily recalling an estimated 467,480 SUVs worldwide to install new a relay circuit that improves fuel-pump relay durability.

FCA US engineers have determined a condition identified in a previous investigation may extend to additional vehicles. The previous investigation, which led to a recall, traced a pattern of repairs to fuel-pump relays that are susceptible to deformation. This may affect fuel-pump function, preventing a vehicle from starting, or leading to engine stall.

**Of the two scenarios, the no-start condition is the more common. FCA US is unaware of any related injuries or accidents.**

The fuel-pump relay is located inside the Totally Integrated Power Module (TIPM), which also helps manage other vehicle functions. **None of these other functions, including air-bag deployment, is affected by the fuel-pump relay.**

The new campaign affects an estimated 338,216 vehicles in the U.S.; 18,991 in Canada; 10,829 in Mexico and 99,444 outside the NAFTA region.

Covered are model-year 2012 and 2013 Dodge Durango full-size SUVs and non-NAFTA 2011 Jeep Grand Cherokee mid-size SUVs equipped with 3.0-liter diesel engines. Current vehicles with EcoDiesel engines are not affected.

FCA US will advise affected customers when they may schedule service, which will be performed at no cost.

In the interim, customers who experience a no-start condition or engine stall are advised to consult their dealers. Owners with questions may call the FCA US Customer Information Center at 1-800-853-1403.

-###-

Additional information and news from Stellantis are available at: <https://media.stellantisnorthamerica.com>