

Contact: Eric Mayne
Trevor Dorchies

Statement: Engine Cover

July 22, 2015, Auburn Hills, Mich. - FCA US LLC is voluntarily recalling an estimated 144,416 crossover utility vehicles (CUVs) in the U.S. to better secure their engine covers.

Engine covers in certain vehicles may become dislodged. If they come in contact with exhaust components, it may pose a fire risk.

This condition was discovered during an FCA US investigation of three incidents in Chile. **In each case, the vehicle had been driven extensively on unpaved or uneven surfaces. The Company is aware of a single related injury, described as minor.**

Affected are 2011-2015 Dodge Journey and Fiat Freemont CUVs equipped with 2.4-liter, four-cylinder engines. FCA US will install upgraded engine-cover retainers in these vehicles. The remedy will be available when customer notification begins next month; service will be performed free of charge.

Vehicles equipped with six-cylinder engines are not affected.

Additional Journey and Freemont populations also are subject to this campaign. They comprise an estimated 43,679 vehicles in Canada; 46,231 in Mexico; and 115,405 outside the NAFTA region.

Of the 349,731 total vehicles subject to this campaign, approximately 10 percent remain in dealer hands.

Customers with questions or concerns may call the FCA US Customer Care Center at 1-800-853-1403.

Indicators of a loose engine cover may include noise from the vehicle's engine compartment, a burning odor and/or a warning light in the instrument cluster. Customers who experience these events are advised to contact their dealers.

-###-

Additional information and news from Stellantis are available at: <https://media.stellantisnorthamerica.com>